

UNIT (CARCASS UNIT)

/		가					FACTOR					[(+ +)/n] × (1+ /20)
	,										(+ + +)/4	
BL - 002	BEARING	25200	2	8400	20000	10080	5	-6	5	8	3	14751
		25200	1	8400	-	20160	5	-6	5	8	3	16422
		25200	1	8400	-	20160	5	-6	5	8	3	16422
		25200	1	8400	-	20160	5	-6	5	8	3	16422
	AOP,MOP	25200	0	8400	-	#####	5	-6	5	8	3	#DIV/0!
BL - 004	BEARING	25200	2	8400	20000	10080	5	-6	5	8	3	15027
		25200	1	8400	-	20160	5	-6	5	8	3	16422
		25200	1	8400	-	20160	5	-6	5	8	3	16422
		25200	1	8400	-	20160	5	-6	5	8	3	16422
	AOP,MOP	25200	0	8400	-	#####	5	-6	5	8	3	#DIV/0!
BL - 007	BEARING	25200	2	8400	20000	10080	5	-6	5	8	3	14751
		25200	1	8400	-	20160	5	-6	5	8	3	16422
		25200	1	8400	-	20160	5	-6	5	8	3	16422
		25200	1	8400	-	20160	5	-6	5	8	3	16422
	AOP,MOP	25200	0	8400	-	#####	5	-6	5	8	3	#DIV/0!
FN - 300	BEARING	25200	1	16800	20000	20160	5	-5	5	8	3.25	22072
		25200	1	16800	-	20160	5	-5	5	8	3.25	21483
		25200	5	4200	-	4032	5	-5	5	8	3.25	4785
		25200	1	16800	-	20160	5	-5	5	8	3.25	21483
FN - 302	BEARING	18240	1	16800	20000	14592	5	-5	5	8	3.25	19915
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	3	4200	-	4864	5	-5	5	8	3.25	5268
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247

) bearing

		가					FACTOR					[(+ +)/2] × (1+ /20)
	,									CBM	(+ + +)/4	
FN-304	BEAR ING	18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	1	4200	-	14592	5	-5	5	8	3.25	10923
		18240	3	16800	-	4864	5	-5	5	8	3.25	12592
FN-306	BEAR ING	25200	1	16800	-	20160	5	-7	5	8	2.75	21021
		25200	1	16800	-	20160	5	-7	5	8	2.75	21021
		25200	4	4200	-	5040	5	-7	5	8	2.75	5255
		25200	1	16800	-	20160	5	-7	5	8	2.75	21021
FN-308	BEAR ING	18240	3	16800	-	4864	5	-5	5	8	3.25	12592
		18240	3	16800	-	4864	5	-5	5	8	3.25	12592
		18240	3	4200	-	4864	5	-5	5	8	3.25	5268
		18240	3	16800	-	4864	5	-5	5	8	3.25	12592
FN-310	BEAR ING	25200	3	8400	-	6720	5	-8	5	8	2.5	8505
		25200	3	8400	-	6720	5	-8	5	8	2.5	8505
		25200	4	4200	-	5040	5	-8	5	8	2.5	5198
		25200	2	8400	-	10080	5	-8	5	8	2.5	10395
FN-312	BEAR ING	25200	2	25200	-	10080	5	-5	5	8	3.25	20507
		25200	2	25200	-	10080	5	-5	5	8	3.25	20507
		25200	6	4200	-	3360	5	-5	5	8	3.25	4394
		25200	2	25200	-	10080	5	-5	5	8	3.25	20507
FN-314	BEAR ING	18240	1	8400	-	14592	5	-7	5	8	2.75	13077
		18240	2	8400	-	7296	5	-7	5	8	2.75	8927
		18240	1	8400	-	14592	5	-7	5	8	2.75	13077
		18240	1	8400	-	14592	5	-7	5	8	2.75	13077

) bearing

		가					FACTOR					[(+ +)/2] × (1+ /20)
	,									CBM	(+ + +)/4	
FN-500A	BEAR ING	25200	2	16800	-	10080	5	-5	5	8	3.25	15624
		25200	2	16800	-	10080	5	-5	5	8	3.25	15624
		25200	5	4200	-	4032	5	-5	5	8	3.25	4785
		25200	2	16800	-	10080	5	-5	5	8	3.25	15624
FN-500B	BEAR ING	25200	2	16800	-	10080	5	-5	5	8	3.25	15624
		25200	2	16800	-	10080	5	-5	5	8	3.25	15624
		25200	5	4200	-	4032	5	-5	5	8	3.25	4785
		25200	2	16800	-	10080	5	-5	5	8	3.25	15624
FN-502	BEAR ING	18240	6	16800	-	2432	5	-7	5	8	2.75	10938
		18240	4	16800	-	3648	5	-7	5	8	2.75	11630
		18240	3	8400	-	4864	5	-7	5	8	2.75	7544
		18240	4	16800	-	3648	5	-7	5	8	2.75	11630
FN-504A	BEAR ING	18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	1	8400	-	14592	5	-5	5	8	3.25	13364
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247
FN-504B	BEAR ING	18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247
		18240	1	8400	-	14592	5	-5	5	8	3.25	13364
		18240	1	16800	-	14592	5	-5	5	8	3.25	18247

) bearing

		가					FACTOR					[(+ +)/2] × (1+ /20)
										CBM	(+ + +)/4	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		8400	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	

)

bear ing

		가					FACTOR					[(+ +)/2] × (1+ /20)
											CBM (+ + +)/4	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		8400	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	

		가					FACTOR					[(+ +)/2] × (1+ /20)
										CBM	(+ + +)/4	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		8400	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	

		가					FACTOR					[(+ +)/2] × (1+ /20)
										CBM	(+ + +)/4	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		4200	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		25200		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		8400	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
		18240		16800	- #DIV/0!	5	-7	5	8	2.75	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
	BEARING	18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		8400	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	
		18240		16800	- #DIV/0!	5	-5	5	8	3.25	#DIV/0!	